BANON HEALTH AND REHABILITATION CE

TEMENT OF DEFICIENCIES

IE OF PROVIDER OR SUPPLIER

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION A BUILDING . 02 - OFFICE BUILDING (X3) DATE SURVEY COMPLETED

11/14/2011 -

TN9502

B. WING STREET ADDRESS, CITY, STATE, ZIP CODE

DEBANUN HEALTH & KEHAB

731 CASTLE HEIGHTS COURT LEBANON, TN 37087

(4) ID REFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
N 832	1200-8-608(2) Building Standards (2) The condition of the physical plant and the overall nursing home environment must be	N 832	N832 1200 Building Standards 1.) The ceiling tile was replaced on	
	developed and maintained in such a manner that the safety and well-being of residents are assured.		11/15/2011. 2.) Other areas of the facility were inspected to ensure compliance with the Fire Safety Standards required.	
.	This Rule is not met as evidenced by: Based on observations, it was determined the facility failed to comply with the Tennessee Department of Health Building Standards.		3.) The Maintenance Supervisor will conduct random inspections to ensure compliance with the TN Department of Health Building Standards.	d i
	The findings included: Observation of the corridor by room 102 on 11/15/11 at 10:30 AM, revealed a stain ceiling tile.	et .	4.) All finding will be reported to QA and A monthly meetings. Subsequent plan of correction will be implemented and developed as needed.	
1	This finding was acknowledged by the administrator and verified by the director of maintenance at the exit conference on 11/15/11.		GOVANA DAMADA ON 12/00/2011	
	. ,		COMPLETED ON 12/09/2011	
				;
			8 8	

n of Halth Care Facilities

ATORY DIRECTOR'S OR PROVIDER SUPPLIER REPRESENTATIVES SIGNATURE

TITLE

(X6) DATE

P16021